

Pre-Purchase Car Inspection Platform

## VEHICLE INSPECTION REPORT

# 2025 Toyota Allion

VIN/Chassis:

**Not Provided**

Registration:

**KDE567K**

Mileage:

**40,000 km**

Asking Price:

**\$5,000,000**

OVERALL

**3.3**

out of 5

### Inspection Details

Inspector: Martin

Date: 12/30/2025

Report ID: 105a8dde

## EXECUTIVE SUMMARY

### Overall Vehicle Assessment:

**3.3/5 - Fair**

Fair - Vehicle needs attention in several areas

### Detailed Section Breakdown

Section	Rating	Status	Key Findings
body	3.7/5	Good	The body shows age-appropriate wear with minor cos...
wheels	4.3/5	Good	Wheels and tires are in good working order. Minor ...
interior	4.0/5	Good	Interior is well-maintained with normal wear patte...
engine	0.0/5	Poor	Significant engine problems detected. Multiple sys...
undercar	4.0/5	Good	Undercarriage shows normal wear. Minor surface rus...
test Drive	4.0/5	Good	The testdrive is in good condition with minor issu...

## MILEAGE & VIN VERIFICATION

Check Item	Status	Notes
Documentation Check	Verified	b
Visual Inspection	Verified	c
OBD ECU Check	Not Verified	N/A
VIN Website Check	Verified	gsd
Foreign Report	Verified	fdafhfah
Overall Assessment	4/5	N/A


## Kenya Mileage Verification Resources:

1. KEBS SMS: Send chassis number to 20023
2. QISJ Website: [www.qisj.co.jp](http://www.qisj.co.jp) (for imported vehicles)
3. Review service records for mileage progression
4. Check NTSA records for vehicle history

## OBD SCAN REPORT & DIAGNOSIS IMAGES




## FOREIGN INSPECTION REPORT IMAGES



## BODY & EXTERIOR INSPECTION

Component	Rating	Condition	Notes
Panel Gaps	4/5	Excellent	affs
Paint & Seams	4/5	Excellent	bSDBDS
Rust Assessment	4/5	No Rust	DSSAGSGA
Body Damage	3/5	Minor Damage	Gasgaag

### BODY INSPECTION PHOTOS



## WHEELS & TIRES INSPECTION

Component	Rating	Condition	Notes
Tread Wear	5/5	Excellent	VSGD
Alignment	4/5	Excellent	GSSG
Turn Lock-to-Lock	4/5	Excellent	DFAHH

### WHEEL & TIRE PHOTOS




PHOTO 1

## INTERIOR & ELECTRONICS INSPECTION

Component	Rating	Condition	Notes
Seats & Upholstery	4/5	Excellent	N/A
Electronics	4/5	Excellent	VVZXDDg
Carpet & Flooring	4/5	Excellent	zb
Trunk & Storage	4/5	Excellent	xcbBZ

### INTERIOR PHOTOS



## ELECTRONICS & INTERIOR FEATURES

Feature	Status	Notes
Dashboard Lights	Yes	N/A
AC / Heating System	Yes	N/A
Power Windows / Mirrors	Yes	N/A
Audio / Navigation	Yes	N/A
Seat Belts	N/A	N/A
Airbags Check	N/A	N/A
Spare Tire / Tools	N/A	N/A

## ENGINE & MECHANICAL INSPECTION

System	Status	Rating	Notes
Engine Performance	Good	0/5	N/A
Oil System	Good	N/A	Oil level and condition assessment
Cooling System	Good	N/A	Coolant level and condition assessment
Electrical System	Good	N/A	Battery, hoses, and belts condition

## ENGINE PHOTOS




PHOTO 1



PHOTO 2


## EXTERIOR LIGHTING & SAFETY

Light System	Status	Notes
Headlights (High/Low)	N/A	N/A
Turn Signals	Yes	N/A
Brake Lights	Yes	N/A
Fog Lights	Yes	N/A
Reverse Lights	Yes	N/A

## UNDERCARRIAGE INSPECTION

Component	Rating	Condition	Notes
Overall Condition	4/5	Excellent	SDggGs
Rust Assessment	4/5	No Rust	dfdg
Suspension	4/5	Excellent	dsgeg
Frame Damage	4/5	No Damage	sdGGDG

### EXTERIOR PHOTOS



## TEST DRIVE ASSESSMENT

Aspect	Rating	Performance	Notes
Acceleration	4/5	Excellent	N/A
Handling	4/5	Excellent	N/A
Braking	4/5	Excellent	N/A
Highway Performance	4/5	Excellent	N/A

## FINAL ASSESSMENT & RECOMMENDATIONS

### Overall Vehicle Assessment:

This vehicle is in fair condition with a rating of 3.3/5. It shows significant wear and will need repairs in several areas.

### Detailed Section Recommendations:

#### body: 3.7/5 (Good)

The body shows age-appropriate wear with minor cosmetic issues that can be addressed through standard detailing or minor bodywork. Areas needing attention: body damage.

#### wheels: 4.3/5 (Good)

Wheels and tires are in good working order. Minor alignment adjustments may be needed. Tires have adequate tread but replacement should be planned within the next year.

#### interior: 4.0/5 (Good)

Interior is well-maintained with normal wear patterns. All essential functions operate correctly.

#### engine: 0.0/5 (Poor)

Significant engine problems detected. Multiple systems require repair including: . Major mechanical overhaul likely needed.

#### undercar: 4.0/5 (Good)

Undercarriage shows normal wear. Minor surface rust may be present but no structural concerns. Some components may need maintenance in the near future.

## FINAL ASSESSMENT & RECOMMENDATIONS (CONTINUED)

### test Drive: 4.0/5 (Good)

The testdrive is in good condition with minor issues.

## INSPECTOR'S FINAL NOTES

## CONCLUSION & INSPECTION VERDICT

FINAL SCORE

**3.3**

### Inspection Recommendation:

Recommended with Caveats - Good condition overall but check the detailed notes for identified issues.

## GLOSSARY & DISCLAIMERS

Term	Definition
Overall Rating	A weighted average scale where 5.0 is excellent condition and 1.0 is severe failure.
Panel Gaps	The spacing between body panels. Uneven gaps often indicate past accidents or frame issues.
OBD ECU Check	Electronic diagnosis using the vehicle's onboard computer to check for stored fault codes.
Chassis Number	The unique 17-digit Vehicle Identification Number (VIN) used to verify vehicle identity.
Test Drive	Real-world evaluation of engine power, transmission smoothness, and suspension performance.

### Important Legal Disclaimer

This report is based on a visual and electronic inspection of the vehicle at the time of the service. PrepurchaseKenya does not disassemble major components and cannot guarantee the internal condition of the engine, gearbox, or differential. This report is for informational purposes only and does not constitute a warranty. PrepurchaseKenya shall not be held liable for any defects that emerge after the inspection or for failures of components that were not accessible or testable during our standard inspection procedure.